1. Running RecurDyn and Creating a New Model

- Double-click the RecurDyn icon on the Desktop to run RecurDyn.
- 2. Enter "Four_Bar_Link" in the Name box and click **OK** to create a new model.



Start RecurDyn	(2)			×
New Model		the mode	I name]
Name	Four_Bar_Lin	Change the		
Unit	MMKS(Millim	eter/Kilogram/Newton/Secon	d) 🔻	Setting
<u>G</u> ravity	-Y		-	Setting
				<u>O</u> K
Open Model				Browse
Recent Mode	els			Icons 💌
projectile_r	notion.rdyn	free_falling_ball.rdyn	Ball_Return	n.rdyn
	14-		ST.	-
🗹 Show 'Star	t RecurDyn' Dia	alog when starting		

2. Creating a Four-Bar

- On the Home tab, in the Working Plane group, enter "50" for the XGridSize and YGridSize coordinates respectively.
- 2. On the toolbar, click the Grid button to display the grid.
- On the Professional tab, in the Body group, click Link, and then select the Point to Point option. Click the origin (0, 0, 0) and then point (400, 500, 0) on the work pane to create Body1.
- 4. Repeat step 3 to create two more bodies.
 - Body2: [400,500,0], [1300,700,0]
 - Body3: [1300,700,0], [1000,0,0]

	dl 🦘 -	P - 💐	≪ 🗢		R	ecurDyn \	V8R3 x64 - [Four_	Bar_Link *]	
Home	ntity	Analysis	Professional	Flexible	Durability	CoLink	AutoDesign	Communicator	Partic
Copy X Delete	XGridSize	50	📐 Angle	🖰 Mass	💾 Merge	🚴 Dele	ete Unused Markers	Database	2
Paste	YGridSize	50	🕞 Radius		Airror 👔	R Clos	se All Dialog	Message	, el
🐰 Cut	Coordinat	e Car 🔻	↔ Distance		Contraction Seload	X Clea	ar Undo History	Window -) Pr
Clipboard	Workin	ig Plane	Meas	ure		Tools		Window	
Entity		•		: +) de 🛈 🦊 🌐	- 🔍 - 🛙	ا • *ه 🚺 🔰 🕽	🗇 - A 🦊	Ŭ.





3. Adjusting the Body Size

- 1. On the work pane, doubleclick Body1 to enter Body Edit mode.
- Select the Link1 body and press P to open the Properties dialog box.
- 3. In the Properties of Link1 dialog box, click the Link tab, and enter "30" for the First Radius and Second Radius.
- 4. Enter "10" for the Depth.
- 5. Click **OK** to close the dialog box.
- 6. Click the Exit button to exit Body Edit mode.
- 7. Repeat the same procedure for both Body2 and Body3.



4. Creating a Joint

- On the Professional tab, in the Joint group, click Revolute.
- 2. On the work pane, click Ground, click **Body1**, and then click the origin **(0, 0, 0)**.
- 3. Repeat step 1 and click **Body1**, click **Body2**, and then click point **(400, 500, 0)** on the work pane.
- 4. Repeat step 1 and click
 Body2, click Body 3, and then click point (1300, 700, 0) on the work pane.
- 5. Repeat step 1 and click **Body3**, click **Ground**, and then click point **(1000, 0, 0)** on the work pane.





5. Checking the Degrees of Freedom

- 1. On the Analysis tab, in the Simulation Type group, click Pre Analysis.
- 2. Click Simulate.
- After running the simulation, scroll through the Message window at the bottom to see if "Kinematic Degree of Freedom = 1" is displayed.

	RecurDyn V8R3 x64 - [Four_Bar_Link.rdyn]	– 🗆 X
Home SubEntity Analysis Profe	sional Flexible Durability CoLink AutoDesign Communicator Particles Toolkit Customize	🔿 ?~_ 🗗 ×
Image: Second operation Image: Second operation Eigen FRA DOE Scend operation	Image: Pause Provide Shape Image: Pause Provide Shape <td< td=""><td></td></td<>	
Simulation	Animation Plot Scope	Post Tool
Entity •	Parameter	🕀 🎯 1 🔹 🖞 🔚 🖞 💽
🖹 Four_Bar_Link.rdyn 🗙 🕒		🗸 🕹 Database 🛛 🕂 🗙
Four_Bar_Link · · · <	Command File	Four_Bar_Link
		· ⊕ for Ground . ⊕ for Body1
	Output File Name	. ⊕ ⊕ Body2 ⊕ ⊕ Body3
	Include State Matrix	
	Display Animation	RevJoint3
	Gravity χ 0. Pv γ -9806.65 Pv z 0. Pv χ .	Couplers Contacts ≡
	Unit Newton - Kilogram - Millimeter - Second	····· ↓ Splines
	Simulate OK Cancel Cancel <td>PPC</td>	PPC
,		
· · · · · · · · · · · · · · · · · · ·		Motion_Expressic
Message No. of Generalized Velocity	ц = 3 - 2	× Wiff.Eq
Kinematic Degree of Freedom = 1		Sensors
Total array size = 5368 Total memory size for array = 0 ME		β BCs 1 Pl <i>αβ</i> DP
Success Process: Array Structure Construct	tion	AR
Redundant Constraint Information For Help, press F1	Car Global X:1100 Y:700 Z:0 Local X:110	

6. Creating a Joint Motion

- On the work pane, select RevJoint1 and press P to display the Properties dialog box. In the Properties of RevJoint1 dialog box, click the Joint tab, and select the Include Motion check box.
- 2. Click **Apply** to apply the changes.

Four	-Bar_L	ink	•	•	•	•	• •			• †						•	
	•	•	•	•	•	•	· ·								•		·
	•	•	•	•	•	•				18				•	•	•	•
	•	•	•	•	•	•	• •			Y	ン・・		· ·	÷	•	•	·
	•	•	•	•	•	•		Pro	operties of R	evJoint1 [Current Unit : N/	 ′kg/mm/s/de	 g]			•	•
•	•	•	•	•	·	•	· •	G	eneral Conn	ector Jo	int		_			•	•
•	·	•	•	•	•	•	•	1	Туре	Revolute						•	•
•	•	•	•	•	•	•	./ ¥	Ĭ	Motion	lotion		Motion				•	•
	•	•	•	•	•	./			Initial Condit	tions						•	•
	·	•	•	·	./			L	Position (PV:I	R)	0. Ve	locity (R/T)	0.				•
	•	•	•	t⁄			• •	L	🗏 Include In	itial Condi	tions 📄	Strict Initial C	onditions			•	•
	•	•	0			•	• •	L	Friction —]	1		•
	•	•		8)		• •	L	lnclude Fr	riction	Slidin		Sliding &	Stiction		•	•
	•	Å		_	•	•	• •	L	Force Display	/	Inactivate			•		•	•
•	•	j <mark>l</mark>		x	•	•	• •								0		•
•	•	y_	-	•	•	•	• •		Scope		OK	Cano	el	Apply	4	/	•
•	•	•	•	•	•	•				· · ·					•	•	•

7. Creating a Motion Expression

- In the Properties of RevJoint1 dialog box, click the Joint tab, and then click the Motion button.
- In the Motion dialog box, click to select
 Displacement (time).
- 3. Click the **EL** button.
- 4. In the Expressions List dialog box, click **Create** in the bottom-left corner.
- In the Expression dialog box, enter "Motion_Expression" in the Name box.
- 6. Enter "360D*TIME" in the Expression input box.
- Click **OK** four times until the Properties of RevJoin1 dialog box closes.

Properties of Revioint1 [Current Unit : N/ka/mm/s/dea 1		Motion
General Connector Joi	nt		Motion
Type Revolute			Type
Motion	Motion		Displacem
- Initial Conditions			Expression
Position (PV:R)	0. Velocity (R/T)	0.	Expression
Friction			
Include Friction	Sliding 🖯 Slidir	ng & Stiction	
Force Display	Inactivate	•	
Scope	OK Cancel	Apply	
xpression List			Expression
No Name	Expression	Value	Name Motion
			360D*TIME
			6
		·	Available □Awc Function ex ⊕Fη Fortran ⊕π Simulat ⊕∞ φ' Displac
4	Inset	Delete	
	ОК	ancel Apply	· · ·



8. Performing Dynamic Analysis

- 1. On the Analysis tab, in the Simulation Type group, click Dyn/Kin.
- In the Dynamic/Kinematic Analysis dialog box, click the General tab, and enter "1" for the End Time.
- 3. Click Simulate to run the simulation.

▶ ▶ ₽ ₽ ₽ ₩ > < < > ₹	RecurDyn V8R3 x64 - [Four_Bar_Link.rdyn]	- 🗆 X
Home SubEntity Analysis Professional	Durability CoLink AutoDesign Communicator Particles Toolkit	Customize 🔊 🔿 🖛 🗙
	ause Mode Shape 1	🔁 Angle 🥜 Entity 🚽 Trace 🛪
	Resume Repeat 1	🖍 Point To Point 🎴 Gap 🛛 📔 Force Display
Eigen FRA DOE Scenario Pre Stati Dyn/Kin	Stop	State Matrix
Simulation Type	Control Animation Control Figen Value Animation Plot	Scope Post Tool
Entity *	Dynamic/Kinematic Analysis	- 🗄 📑 📿 👂 🛞 🐼 1 🖞 🧮 🐂 🖞
Reverse Four Bar Link, rdyn ×	General Parameter	V Database 4 ×
Four-Bord ink		Y Four Bar Link
Time = Initial State	End Time	
		Bodies
	Step 100. Pv ·	· · · · · · · · · · · · · · · · · · ·
	Plot Multiplier Step Factor 1. Pv .	Bodyl
	Output File Name	
		· · · · · ·
· · · · · · · · · · · · · · · · · ·	_ Include Include	😥 🔮 RevJoint1
/ /	Static Analysis	RevJoint2
		Bevloint3
	Eigenvalue Analysis	
	State Matrix	Couplers
	Frequency Response Analysis	Contacts
		Requests
	Hide RecurDyn during Simulation	· · · · · · · · · · · · · · · · · · ·
		α PV
	Display Animation	· · · · · · · PPC
┃	C Gravity	••••••••
		AB Strings
		Motion Expression
	Newton - Kilogram - Millimeter - Second	
Moscogo		
Message		T A War.Eq
Anglusia Time Information	Simulate OK Cancel	Scopes
Starting Time/Date = 15:43:56 / 2016.2.11		BCs
Ending Time/Date = 15:43:56 / 2016.2.11 CPU Time = 0.8 Second (0 hr. 0 min 0.8 sec.)		- PI
Analysis is accomplished successfully		AR AR
		Subsystems
For Help, press F1	Car Global X:1700 Y:600 Z:0	Local X:1700 Y:600 N/kg/mm/s

9. Playing the Animation

1. On the Analysis tab, in the Animation Control group, use the Play and Stop buttons to play the animation of the analysis results.



10. Analytical Solution

- Equation for calculating the degrees of freedom
- Example calculation of the degrees of freedom of a fourbar linkage

The degrees of freedom of a model are determined by the number of rigid bodies, and the number and type of joints. Each object has a total of 6 degrees of freedom. You can calculate the total number of constraint equations by multiplying the number of constraint equations per joint type with the number of joints, and then adding the products of all the joint types.

Calculating the degrees of freedom of a system : $\frac{\sum Body Num. \times 6}{\sum Jnt Num \times Cnst Num.}$ System DOF

The following is an example calculation of the degrees of freedom of a four-bar linkage model. The total degree of freedom of the model is 1. This example is a desirable modeling of a four-bar linkage system.

